



## Service Info



# Change affecting hydraulic bucket tappet

Manufacturers: Alfa Romeo, Fiat, Lancia, Rover

**Models:**

Alfa Romeo: 145, 146, 147, 155, 156, 166, GT, GTV, Spider

Fiat: Barchetta, Brava, Bravo I, Coupe, Doblo, Marea, Multipla, Palio, Punto, Siena, Stilo

Lancia: Kappa, Lybra, Thesis

Rover: 100, 200, 400, 600, 800, Carbrio

Engines: 1.6, 1.6 16V, 1.7 T.S. 16V, 1.8 16V, 2.0, 2.0 16V, 2.0 20V, 2.4 20V

Part no.: 420 0050 10  
420 0208 10

**OE number:**

Fiat: 464103078  
73503122



Figure 1: Hydraulic bucket tappet: left: old version, right: new version

The vehicle manufacturers for the models specified above have changed the installation height of the hydraulic bucket tappet. Accordingly, Schaeffler Automotive Aftermarket is offering a modified version in the aftermarket.

The new hydraulic bucket tappet is 2 mm higher. Although the installation height is now different, the new bucket tappet can be fitted in the specified engines without any problems. The two versions do not differ in terms of their technical function.

Observe the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under [www.schaeffler-aftermarket.com](http://www.schaeffler-aftermarket.com) or [www.RepXpert.com](http://www.RepXpert.com).



Figure 2: Hydraulic bucket tappet, left: old version, right: new version

Phone: +44 (0) 14 32 264 264\*  
Fax: +44 (0) 14 32 375 760  
hfd-info@schaeffler.com  
[www.schaeffler-aftermarket.com](http://www.schaeffler-aftermarket.com)

\* Calls from within the UK 08457 001100

**SCHAEFFLER**  
AUTOMOTIVE AFTERMARKET

